



[4910-13-P]

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2014-1123; Directorate Identifier 2014-CE-037-AD]

RIN 2120-AA64

Airworthiness Directives; GA 8 Airvan (Pty) Ltd Airplanes

AGENCY: Federal Aviation Administration (FAA), Department of Transportation (DOT).

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: We propose to adopt a new airworthiness directive (AD) for GA 8 Airvan (Pty) Ltd Model GA8-TC320 airplanes. This proposed AD results from mandatory continuing airworthiness information (MCAI) originated by an aviation authority of another country to identify and correct an unsafe condition on an aviation product. The MCAI describes the unsafe condition as missing required engine mount fire seal washers, which could reduce the engine retention capability in the event of a fire. We are issuing this proposed AD to require actions to address the unsafe condition on these products.

DATES: We must receive comments on this proposed AD by [INSERT DATE 45 DAYS AFTER DATE OF PUBLICATION IN THE FEDERAL REGISTER].

ADDRESSES: You may send comments by any of the following methods:

- Federal eRulemaking Portal: Go to <http://www.regulations.gov>. Follow the instructions for submitting comments.
- Fax: (202) 493-2251.
- Mail: U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue, SE, Washington, DC 20590.

- Hand Delivery: U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue, SE., Washington, DC 20590, between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

For service information identified in this proposed AD, contact GA 8 Airvan (Pty) Ltd, c/o GippsAero Pty Ltd, Attn: Technical Services, P.O. Box 881, Morwell Victoria 3840, Australia; telephone: + 61 03 5172 1200; fax: +61 03 5172 1201; email: techpubs@gippsaero.com; Internet: <http://www.gippsaero.com/customer-support/technical-publications.aspx>. You may review this referenced service information at the FAA, Small Airplane Directorate, 901 Locust, Kansas City, Missouri 64106. For information on the availability of this material at the FAA, call (816) 329-4148.

Examining the AD Docket

You may examine the AD docket on the Internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2014-1123; or in person at the Docket Management Facility between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this proposed AD, the regulatory evaluation, any comments received, and other information. The street address for the Docket Office (telephone (800) 647-5527) is in the ADDRESSES section. Comments will be available in the AD docket shortly after receipt.

FOR FURTHER INFORMATION CONTACT: Doug Rudolph, Aerospace Engineer, FAA, Small Airplane Directorate, 901 Locust, Room 301, Kansas City, Missouri 64106; telephone: (816) 329-4059; fax: (816) 329-4090; email: doug.rudolph@faa.gov.

SUPPLEMENTARY INFORMATION:

Comments Invited

We invite you to send any written relevant data, views, or arguments about this proposed AD. Send your comments to an address listed under the ADDRESSES section. Include “Docket No. FAA-2014-1123; Directorate Identifier 2014-CE-037-AD” at the beginning of your comments. We specifically invite comments on the overall regulatory, economic, environmental, and energy aspects of this proposed AD. We will consider all comments received by the closing date and may amend this proposed AD because of those comments.

We will post all comments we receive, without change, to <http://regulations.gov>, including any personal information you provide. We will also post a report summarizing each substantive verbal contact we receive about this proposed AD.

Discussion

The Civil Aviation Safety Authority (CASA), which is the aviation authority for Australia, has issued AD No. AD/GA8/8, dated November 24, 2014 (referred to after this as “the MCAI”), to correct an unsafe condition for GA 8 Airvan (Pty) Ltd Model GA8-TC320 airplanes and was based on mandatory continuing airworthiness information originated by an aviation authority of another country. The MCAI states:

A recent review of the engine mount installation on the GA8-TC 320 aircraft has highlighted the omission of engine mount fire seal washers during the assembly process.

The current engine mount configuration does not meet the certification basis for the aircraft, specifically regulation 23.865 of the Federal Aviation Regulations of the United States of America, where engine mounts located in designated fire zones are required to be suitably shielded so that they are capable of withstanding the effects of a fire.

The Gippsland Aeronautics GA8-TC 320 aircraft require the installation of an approved steel washer at each of the engine mount locations to address a potential risk of reduced engine retention capability in the event of a fire.

You may examine the MCAI on the Internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2014-1123.

Relevant Service Information

GippsAero has issued Mandatory Service Bulletin SB-GA8-2014-115, Issue 1, dated October 6, 2014. The actions described in this service information are intended to correct the unsafe condition identified in the MCAI. The service information describes procedures for inspecting the orientation of the engine isolator mounts to verify proper installation, re-installing if necessary, and installing steel washers on the forward side of each side of the engine isolator mounts.

FAA's Determination and Requirements of the Proposed AD

This product has been approved by the aviation authority of another country, and is approved for operation in the United States. Pursuant to our bilateral agreement with this State of Design Authority, they have notified us of the unsafe condition described in the MCAI and service information referenced above. We are proposing this AD because we evaluated all information and determined the unsafe condition exists and is likely to exist or develop on other products of the same type design.

Costs of Compliance

We estimate that this proposed AD will affect 13 products of U.S. registry. We also estimate that it would take about 5 work-hours per product to comply with the basic requirements of this proposed AD. The average labor rate is \$85 per work-hour. Required parts would cost about \$10 per product.

Based on these figures, we estimate the cost of the proposed AD on U.S. operators to be \$5,655, or \$435 per product.

According to the manufacturer, all of the costs of this proposed AD may be covered under warranty, thereby reducing the cost impact on affected individuals. We do not control warranty coverage for affected individuals. As a result, we have included all costs in our cost estimate.

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. "Subtitle VII: Aviation Programs," describes in more detail the scope of the Agency's authority.

We are issuing this rulemaking under the authority described in "Subtitle VII, Part A, Subpart III, Section 44701: General requirements." Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

We determined that this proposed AD would not have federalism implications under Executive Order 13132. This proposed AD would not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify this proposed regulation:

- (1) Is not a "significant regulatory action" under Executive Order 12866,
- (2) Is not a "significant rule" under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979),
- (3) Will not affect intrastate aviation in Alaska, and
- (4) Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

The Proposed Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA proposes to amend 14 CFR part 39 as follows:

PART 39 - AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

2. Amend § 39.13 by adding the following new AD:

GA 8 Airvan (Pty) Ltd: Docket No. FAA-2014-1123; Directorate Identifier 2014-CE-037-AD.

(a) Comments Due Date

We must receive comments by [INSERT DATE 45 DAYS AFTER DATE OF PUBLICATION IN THE FEDERAL REGISTER].

(b) Affected ADs

None.

(c) Applicability

This AD applies to GA8 Airvan (Pty) Ltd GA8-TC320 airplanes, all serial numbers affected, certificated in any category.

(d) Subject

Air Transport Association of America (ATA) Code 71: Power Plant.

(e) Reason

This AD was prompted by mandatory continuing airworthiness information (MCAI) originated by an aviation authority of another country to identify and correct an unsafe condition on an aviation product. The MCAI describes the unsafe condition as missing required engine mount fire seal washers, which could reduce the engine retention capability in the event of a fire. We are issuing this AD to inspect the engine mounts to verify they have been installed with the correct orientation and install steel washers at each isolator mount location, which, if not done, could result in reduced engine retention capability in the event of a fire.

(f) Actions and Compliance

Unless already done, do the following actions in paragraphs (f)(1) through (f)(4) of this AD:

(1) Within the next 300 hours time-in-service after the effective date of this AD or within the next 12 months after the effective date of this AD, whichever occurs first, inspect the orientation of the engine isolator mounts to verify that the mounts have been installed properly following the Accomplishment Instructions in GippsAero Mandatory Service Bulletin SB-GA8-2014-115, Issue 1, dated October 6, 2014.

(2) Before reinstalling the engine isolator mounts following the inspection required in paragraph (f)(1) of this AD, before further flight, install a part number J-2218-61 steel washer on the forward side of each of the four engine isolator mounts, following the Accomplishment Instructions in GippsAero Mandatory Service Bulletin SB-GA8-2014-115, Issue 1, dated October 6, 2014.

(3) If after the inspection required in paragraph (f)(1) of this AD, any of the engine isolator mounts are found to not comply with the specifications found in the Accomplishment Instructions of GippsAero Mandatory Service Bulletin SB-GA8-2014-115, Issue 1, dated October 6, 2014, before further flight, re-install the isolators to the correct orientation, or if damage is found, replace with airworthy parts.

(g) Other FAA AD Provisions

The following provisions also apply to this AD:

(1) Alternative Methods of Compliance (AMOCs): The Manager, Standards Office, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. Send information to ATTN: Doug Rudolph, Aerospace Engineer, FAA, Small Airplane Directorate, 901 Locust, Room 301, Kansas City, Missouri 64106; telephone: (816) 329-4059; fax: (816) 329-4090; email: doug.rudolph@faa.gov. Before using any approved AMOC on any airplane to which the AMOC applies, notify your appropriate principal inspector (PI) in the FAA Flight Standards District Office (FSDO), or lacking a PI, your local FSDO.

(2) Airworthy Product: For any requirement in this AD to obtain corrective actions from a manufacturer or other source, use these actions if they are FAA-approved. Corrective actions are considered FAA-approved if they are approved by the State of Design Authority (or their delegated agent). You are required to assure the product is airworthy before it is returned to service.

(3) Reporting Requirements: For any reporting requirement in this AD, a federal agency may not conduct or sponsor, and a person is not required to respond to, nor shall a person be subject to a penalty for failure to comply with a collection of information subject to the requirements of the Paperwork Reduction Act unless that collection of information displays a current valid OMB Control Number. The OMB Control Number for this information collection is 2120-0056. Public reporting for this collection of information is estimated to be approximately 5 minutes per response, including the time for reviewing instructions, completing and reviewing the collection of information. All responses to this collection of information are mandatory. Comments concerning the accuracy of this burden and suggestions for reducing the burden should be directed to the FAA at: 800 Independence Ave. SW, Washington, DC 20591, Attn: Information Collection Clearance Officer, AES-200.

(h) Related Information

Refer to MCAI Civil Aviation Safety Authority (CASA) AD No. AD/GA8/8, dated November 24, 2014. You may examine the MCAI on the Internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2014-1123. For service information related to this AD, contact GA 8 Airvan (Pty) Ltd, c/o GippsAero Pty Ltd, Attn: Technical Services, P.O. Box 881, Morwell Victoria 3840, Australia; telephone: + 61 03 5172 1200; fax: +61 03 5172 1201; email: techpubs@gippsaero.com; Internet: <http://www.gippsaero.com/customer-support/technical-publications.aspx>. You may review this referenced service information at the FAA, Small Airplane Directorate, 901 Locust, Kansas City, Missouri 64106. For information on the availability of this material at the FAA, call (816) 329-4148. Issued in Kansas City, Missouri, on December 29, 2014.

Robert Busto,
Acting Manager, Small Airplane Directorate,
Aircraft Certification Service.

[FR Doc. 2014-30910 Filed 01/05/2015 at 8:45 am; Publication Date: 01/06/2015]